Attachment B RFP 26039

Base Bid: (21) Total magnetometers needed
-(2) Spare Magnetometers to troubleshoot if necessary